

## Problem Locations Not Included in Six Year Plan Projects

Route	Location	Description	Comment	Status	Category
US 42	Industrial Road to I-75	Add westbound lane	CMAQ application; awaiting authorization	Pending	Capacity/Congestion
KY 18	Oakbrook Drive	Relocate to intersect with new S. Airfield Road	Working with homeowners association	Ongoing	Capacity/Congestion
KY 536	Camp Ernst Road	Address guardrail crashes	Earthen bank and vegetation removal	Unscheduled	Safety
US 42	South of Beaver Road	Improve sight distance	Low shoulder and ravine on westbound side	Unscheduled	Safety
KY 338	Paddock Drive to Triple Crown	Guardrail improvements	City trash receptacle blocking westbound view	Unscheduled	Safety
US 25	Sanders Drive	Remove sight distance obstruction		Unscheduled	Safety
KY 2846	East of KY 237	Correct dip in pavement	Embankment blocks view to north from EB approach	Unscheduled	Safety
US 42	Rice Pike	Improve sight distance		Unscheduled	Safety
KY 18	KY 842	Intersection improvements	Add eastbound right turn lane and provide NB dual left turn lane	Unscheduled	Capacity/Congestion
US 42	Mall Road	Intersection improvements	Add second eastbound left turn lane	Unscheduled	Capacity/Congestion
KY 842	North of US 42	Access management	Redesign/relocate driveway for Grammas Center and BP Gas Station	Unscheduled	Safety
KY 18	KY 338	Intersection improvements	Study new lane configuration and/or signalization	Unscheduled	Capacity/Congestion
KY 18	Taylor Drive (east)	Intersection improvements	Lane configuration improvements	Unscheduled	Both
KY 18	KY 237 to Limaburg Road	Access management	Study eliminating median breaks	Unscheduled	Both
KY 18	KY 237 to Zig Zag Road	Traffic control	Speed study to evaluate change from 55 mph to 45 mph	Unscheduled	Safety
KY 18	Merchants Street	Conduct signal warrant analysis	Study need for new signal	Unscheduled	Capacity/Congestion
KY 18	Greenview Drive/Ridge Road	Conduct signal warrant analysis	Study signal removal	Unscheduled	Both
KY 8	East of Taylorsport	Drainage improvements	Examine ditches, etc.	Unscheduled	Safety
KY 237	Gateway Blvd.	Signal improvements	Study and change actuation as needed	Unscheduled	Capacity/Congestion
KY 237	Conrad Lane	Signal improvements	Study need for left turn arrows	Unscheduled	Capacity/Congestion
KY 842	Bankers Street	Conduct signal warrant analysis	Study need for new signal and/or turning movement restrictions	Unscheduled	Both
KY 18	Woodspoint Drive/Action Blvd.	Enforcement	Enforce left turn restrictions	Unscheduled	Both
KY 18	Commerce Drive	Intersection improvements	Congestion and difficulty making left turns	Unscheduled	Both
US 25	South of US 42	Access management	Difficulty accessing professional offices on east side	Unscheduled	Both
US 42	Ewing Blvd.	Intersection improvements	Study signal improvements and south leg stacking	Unscheduled	Capacity/Congestion
US 42	I-75 Interchange NB Exit	Interchange improvements	Stacking on ramp and sight distance problems	Unscheduled	Both
Mall Road	Plaza Blvd.	Conduct signal warrant analysis	Study geometrics and grades	Unscheduled	Safety
Mall Road	Mall Road Square	Geometric improvements	Vary signal timing by time of day	Unscheduled	Both
US 42	KY 842	Signal Improvements	Trim hedges that block visibility	Unscheduled	Capacity/Congestion
Connector Drive	Next to Toys 'R Us	Sight distance improvements		Unscheduled	Safety

